


SIL-SM.009 0

Hydraulic (Subsea) Shuttle Valves

Compiled By : G. Elliott,

Date: 11/3/2014



Bifold Group

Bifold Bifold FluidPower Bifold Subsea Bifold Marshalsea Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4777 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture W4y, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 321081 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.bifold.co.uk **USA Office** Bifold Fluidpower Ltd I1490 Westheimer, Suite 850, Houston, TX 77077. Tel: +1 (713) 783 4253 Fax: +1(713) 783 40567 Email: marketing@bifold.co.uk Web: www.bifold.co.uk

Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk





Contents

	Terminology Definitions	3
	Acronyms & Abbreviations	.4
1. Introdu	ction	.5
1.1	Scope	.5
1.2	Relevant Standards	.5
1.3	Other related documents and papers	.5
2. Device D	escription	.5
2.1	Safety Function	5
2.2	Environmental Limits	5
2.3	Application Limits	5
2.4	Design Verification	5
2.5	Sil Capability	6
2.5.1	Systematic Integrity	6
2.5.2	Random Integrity	.6
3. Installatio	n & Commissioning	7
3.1	Installation	.8
3.2	Proof testing	8
3.3	Repair & Replacement	.9
3.4	Useful Life	.9
3.5	Reporting Concerns to Bifold	.9

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4777 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 331061 Fax: +44 (0) 1823 332382 Email: info@marshalsea.co.uk Web: www.bifold.co.uk USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 7707, Tei: +1 (713) 783 4253 Fax: +1 (713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk

Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tei: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk



Terminology Definitions:

Description	Explanation	
Safety:	Freedom from unacceptable risk of harm	
Functional Safety:	The ability of a system to carry out the actions necessary to achieve or to maintain a defined safe state for the equipment / machinery / plant / apparatus under control of the system.	
Basic Safety:The equipment must be designed and manufactured such that it pro against risk of damage to persons by electrical shock and other haza against resulting fire and explosion. The protection must be effective all conditions of the nominal operation and under single fault conditions		
Safety Assessment:	<i>ment:</i> The investigation to arrive at a judgment - based on evidence - of the safe achieved by safety-related systems.	
Fail-Safe State:	State where solenoid valve is de-energized and spring is extended.	
Safe FailureFailure that causes the value to go to the defined fail-safe state with demand from the process.		
Dangerous Failure	Failure that does not respond to a demand from the process (i.e. being unable to go to the defined fail-safe state).	
Dangerous Undetected Failure	Failure that is dangerous and that is not being diagnosed by automatic stroke testing.	
Dangerous Detected:	Failure that is dangerous but is detected by automatic stroke testing.	
Fail Annunciation	Failure that does not cause a false trip or prevent the safety function but	
Undetected	does cause loss of an automatic diagnostic and is not detected by another diagnostic.	
Fail Annunciation Detected:Failure that does not cause a false trip or prevent the safety function does cause loss of an automatic diagnostic or false diagnostic indication		
Fail No Effect:	Failure of a component that is part of the safety function but that has no effect on the safety function.	
Low demand mode: Mode, where the frequency of demands for operation made on a sate related system is no greater than twice the proof test frequency.		

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4777 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tei: +44 (0) 1823 331061 Fax: +44 (0) 1823 332382 Email: info@marshalsea.co.uk Web: www.bifold.co.uk USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 7707. Tel: +1 (713) 783 0453 Fax: +1(713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk

Bifold

Acronyms / Abbreviations

Acronym / Abbreviation	Description	Explanation
CCF	Common Cause Failure	A common cause failure is one in which a single failure or condition affects the operation of multiple devices that would otherwise be considered independent. Common cause failures can result in the SIS failing to function when there is a process demand.
FITS	Failures in Time	The number of failures that can be expected in one billion (10 ⁹) device-hours of operation.
FMEDA	Failure Modes, Effects & Diagnostics Analysis	A method of assessing a hardware device in order to predict failure rates and hence determine the applicable SFF.
HFT	Hardware Fault Tolerance	Ability of a functional device to continue to perform a required function when faults or errors are prevailing.
LOPA	Layers of Protection Analysis	LOPA is a methodology for hazard evaluation and risk assessment.
MTBF	Mean Time Between Failures	Mean time Between Failures. $(1/\lambda)$.
MTTR	Mean Time To Repair	Mean time between the occurrence of an error in a unit or system and its repair.
OIM	Operation & Installation Manual	Information on correct installation, maintenance and testing.
PFD	Probability of Failure on Demand	Probability of failures for a safety function on demand
PFDavg	Average Probability of Failure on Demand	Average Probability of failures for a safety function on demand
ΡΤΙ	Proof Test Interval	The time between diagnostic testing or Partial Stroke Testing.
SIL	Safety Integrity Level	The international standard IEC61508 defines four discrete Safety Integrity Levels (SIL 1 to SIL 4). Each level corresponds to a range of probability for the failure of a safety function. The higher the SIL level the lower the probability that they will not perform the required safety function
SFF	Safe Failure Fraction	The proportion of non-hazardous failures.
λ	Failure Rate	Failure Rate – the ratio of the total number of failures in a given time period
λd	Dangerous Failure Rate	Failure Rate of Dangerous failures (per hour).
λdd	Dangerous Detected Failure rate	Failure Rate of Dangerous failures detected by diagnostic testing (per hour).
λου	Dangerous Undetected Failure Rate	Failure Rate of Dangerous failures Undetected by diagnostic testing (per hour).
λs	Safe Failure Rate	Failure Rate of Safe failures (per hour).

Bifold Group

Bitold Bitold FluidPower Bitold Subseq Bitold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 331081 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.bifold.co.uk

USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 7707, Tel: +1 (713) 783 4253 Fax: +1(713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk



I. Introduction

I.I Purpose & Scope

This manual provides the results of a functional safety assessment of Subsea Shuttle Valves, by TUV in accordance with IEC61508: ed2: 2010.

The results of this provides the safety instrumentation engineer with the required failure data as per IEC61508 / IEC 61511, and confidence that sufficient attention has been given to systematic failures during the development of the device.

I.2 Relevant Standards

IEC 61508, IEC61511.

1.3 Other Related documents and papers

TUV FMEDA Report : V 464.01/14

Device	Document ID	Document Type
FPS15, FPS30		Data Sheet
FPS15, FPS30		Operating & Installation Manual
FPS15, FPS30	19- Shuttle Valves (October 12)	Product Catalogue

2. Device Description

A Range of Subsea rated Hydraulic Shuttle valves.

Non-biased shuttle valves are two input, single output valves that are completely pressure controlled.

The higher input pressure creates a pressure differential causing flow through the valve while the system pressure holds the other input port closed.

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4777 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 320381 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.biold.co.uk USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 77077. Tel: +1 (713) 783 4253 Fax: +1 (713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk



2.1 Safety Function

In the event of a system failure, and the supply to either port P1 or P2 fails (closes), the shuttle valve will operate to enable the safe shut down of the system by enabling flow from the active port to Port A.

The Hydraulic (Subsea) Shuttle Valves are designed to be part of a final element subsystem as defined by IEC61508 and the achieved SIL level of the designed function must be verified by the system designer.

2.2 Environmental Limits

The designer of a SIF must verify that the product is rated for use within the expected environmental limits.

For SIL rated valves the minimum operating temperature is -18°C.

Refer to Bifold Product Catalogue for more information.

2.3 Application Limits

The materials of construction are specified in the various Bifold Catalogues and Data Sheets. Maximum Operating Pressure is up to 410 Bar.

2.4 Design Verification

A Failure Mode, Effects, and Diagnostics Analysis (FMEDA) report has been carried out independently by Exida.com and is available from Bifold on request.

The achieved Safety Integrity Level (SIL) of an entire Safety Instrumented Function (SIF) design must be verified by the designer via a calculation of PFD_{average} considering architecture, proof test interval, proof test effectiveness, any automatic diagnostics, average repair time and the specific failure rates of all products included in the SIF. Each subsystem must be checked to assure compliance with minimum hardware fault tolerance (HFT) requirements.

When using Hydraulic (Subsea) Shuttle Valves in a redundant configuration, a common cause factor of **0.1** should be included in safety integrity calculations.

The failure rate data listed the FMEDA report is only valid for the useful life time of a valve. The failure rates will increase sometime after this time period.

Reliability calculations based on the data listed in the FMEDA report for mission times beyond the lifetime may yield results that are too optimistic, i.e. the calculated Safety Integrity Level will not be achieved.

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4777 Fax: +44 (0) 161 345 4780 Emailt: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 320381 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.biold.co.uk

USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 77077. Tel: +1 (713) 783 4253 Fax: +1 (713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 407-1475, Singapore 3109075 Tel: +56 5735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk



2.5 SIL Capability

2.5.1 Systematic Integrity

The product has met manufacturers design process requirements of **Safety Integrity Level** (SIL) 3.

These are intended to achieve sufficient integrity against systematic errors of design by the manufacturer.

A Safety Instrumented Function (SIF) designed with this product must not be used at a SIL level higher than the statement without "prior use" justification by end user or diverse technology redundancy in the design.

+λdu)	+λdu)
Please Refer to the TUV report for the Specific Please Refer to the TUV report for	for the Specific
Lambda Values Lambda Values	

2.5.2 Random Integrity

The valve is a **Type A Device**.

Therefore, based on the SFF between 60% and 90%, when the valve is used as the only component in a final element subassembly, a design can meet SIL 2 @ HFT=0.

When the final element assembly consists of many components (Solenoid Valve, quick exhaust valve, etc.) the SIL must be verified for the entire assembly using failure rates from all components.

This analysis must account for any hardware fault tolerance and architecture constraints.

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Warshalseq Bifold Group Ltd, Head Office, Broadgate, Oldham Broadway Business Park, Chadderton, Greater Manchester OL9 9XA Tel: +44 (0) 161 345 4780 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 320381 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.biold.co.uk USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 77077. Tel: +1 (713) 783 4253 Fax: +1 (713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk



3.0 Installation and Commissioning

3.1 Installation

The device must be installed per standard practices outlined in the Installation Manual. The environment must be checked to ensure that environmental conditions do not exceed the ratings.

The device must be accessible for physical inspection.

3.2 Proof Testing

The Device should be subjected to a full test at least once every 12 months (or more frequently based on the desired PFDavg calculations – Ref Section 2.4). This would normally be conducted as parts of a proof test or partial stroke test for the actuator under control. Partial stroke testing of the Safety Instrumented Function (SIF) must provide a full test of the device.

According to section 7.4.3.2.2 f) of IEC61508-2, proof tests shall be undertaken to reveal dangerous faults which are undetected by diagnostic tests. This means that it is necessary specify how dangerous undetected faults which have been noted during the FMEDA can be detected during proof testing.

3.2.1 Suggested Proof Test

The suggested proof test consists of a full stroke of the device, as described in the table below. This test will detect of the possible DU failures of the Hydraulic (Subsea) Shuttle Valves, when PVST is not being performed.

Step	Action
I	Bypass the safety function and take appropriate action to avoid a false trip
2	Send a signal to the device to perform a full stroke and verify that this is achieved.
3	Inspect the device for any visible damage or contamination.
4	Remove the bypass otherwise restore normal operation.

3.3 Repair and Replacement

Repair procedures must be implemented as per the Operation, Installation and Maintenance Manual for the device.

The SIL rating of the valve will be voided if the repair is not performed with Genuine Bifold parts and serviced by a competent person.

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Minrshalseq Bifold Group Ltd, Head Office, Greenside Way, Middleton, Manchester M24 ISW. Tel: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture W4y, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tel: +44 (0) 1823 321081 Fax: +44 (0) 1823 32382 Email: info@marshalsea.co.uk Web: www.bifold.co.uk

USA Office Bifold Fluidpower Ltd 11490 Westheimer, Suite 850, Houston, TX 77077. Tel: +1 (713) 783 4253 Fax: +1 (713) 783 4253 Fax: +1 (713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@blfold.co.uk Web: www.bifold.co.uk



3.4 Useful Lifetime for the Device.

The useful lifetime of the Hydraulic (Subsea) Shuttle Valves is 20 years or 20,000 cycles - whichever occurs first.

3.5 Reporting Concerns to Bifold

All faults to be reported to Bifold for recording purposes, by contacting the Quality Department at the supplying facility listed at the bottom of the page. All defective devices must be returned to Bifold for investigation and rectification by the Manufacturer. A Valve Return and Service Report form (VRSR) – available upon request, from the supplying facility -(Contact details at the foot of this page) must be completed and returned with the device.

Bifold Group

Bifold Bifold FluidPower Bifold Subseq Bifold Minrshalseq Bifold Group Ltd, Head Office, Greenside Way, Middleton, Manchester M24 ISW. Tel: +44 (0) 161 345 4770 Fax: +44 (0) 161 345 4780 Email: marketing@bifold.co.uk Web: wwwbifold.co.uk Marshalsea Hydraulics Ltd Marshalsea House, Venture Way, Priorswood Industrial Estate, Taunton, Somerset, TA2 8DE. UK. Tei: +44 (0) 1823 331081 Fax: +44 (0) 1823 332382 Email: info@marshalsea.co.uk Web: www.biold.co.uk USA Office Bifold Fluidpower Ltd I1490 Vestheimer, Suite 850, Houston, TX 77077. Tei: +1 (713) 783 4253 Fax: +1(713) 783 0067 Email: marketing@bifold.co.uk Web: www.bifold.co.uk

Singapore Office Bifold Fluidpower Ltd Toa Payoh Industrial Park, Block 1002, Lorong 8 #07-1475, Singapore 3109075 Tel: +65 6735 1323 Fax: +65 6735 1367 Email: marketing@bifold.co.uk Web: www.bifold.co.uk